est. 1967

HAMILTON CUSTOM MADE SECURITY

PRODUCT NOTIFICATION

Notification Number: PN82120-1	Released / Effective Date: N/A
Product Name: HA47 turbine	Product Part Number:99-998
Purpose of Change: Issues with operation of the HA47 turbine pack	Description: Issue with internal shifter on HA47 turbine pack causing functionality issues.

***** Product Notification Message *****

We have found there to be a few cases of issues with our new HA47 turbine packs. The issue has been seen both directly out of the box and intermittently. In these cases, the turbine will turn on correctly, but will not travel from the customer unit to the teller unit. The issue has been traced to the internal shifter in the turbine pack. For assistance with this issue, please call **Technical Support at 513-262-7763.**



Hamilton, 7775 Cooper Road, Cincinnati, Ohio 45242 Phone (513) 874-3733 Fax (513) 874-3967